

NOTE: During each assembly step, ensure that all bolts and nuts are in place and partially threaded in before completely tightening any one bolt.




Part list	of step 1	
ITEM		D

ITEM	DESCRIPTION	QTY
Α	ASSY,WEIGHT SIDE FRAME	1
В	ASSY, MAIN FRAME	1
1	FOOT COVER 2"x2.75"	4
2	TOP CROSS BRACE	1
3	BOTTOM CROSS BRACE	1
a <b>1</b>	BOLT,HHCS,1/2"-13*3 1/2", L=89mm	8
b <b>1</b>	WASHER,FLAT,1/2"	16
с1	LOCK NUT 1/2"-13	8




NOTE: During each assembly step, ensure that all bolts and nuts are in place and partially threaded in before completely tightening any one bolt.




Above shows	step 2	? asseml	bled ai	nd comp	leted.
-------------	--------	----------	---------	---------	--------




are not	or stop i	
ITEM	DESCRIPTION	QTY
С	ASSY,ARM	1
D	ASSY,BOOSTER	1
E	ASSY,FOOTLEVER	1
F	ASSY,PULL	1
4	CHROME WASHER ( Φ35*Φ11*5t )	5
5	CONNECT PLATE	2
6	NYLON COVER	2
8	AXLE(Ø25*315)	2
9	GAS SPRING(30kg)	1
10	AXLE(Ø25*86)	1
11	CHROME WASHER ( Φ42*Φ13*4t )	2
<b>a</b> 2	BOLT,BHCS,3/8"-16*3/4", L=18mm	5
a <b>3</b>	BOLT,HHCS,1/2"-13*1", L=25mm	2
a <b>4</b>	BOLT,HHCS,M8*40mm	2
<b>a</b> 11	BOLT,BHCS,5/16"-18*3/4", L=16mm	1
b <b>4</b>	WASHER,FLAT,M8	4
c <b>4</b>	LOCK NUT M8	2
<b>d</b> 1	LOCK WASHER Ø13mm	2
	A	•




NOTE: During each assembly step, ensure that all bolts and nuts are in place and partially threaded in before completely tightening any one bolt.




NOTE: During each assembly step, ensure that all bolts and nuts are in place and partially threaded in before completely tightening any one bolt.




Part list	of step 1	
ITEM	DESCRIPTION	QTY
G	ASSY,TOP WEIGHT	1
17	WEIGHT STACK	19
18	SELECTOR PIN	1
19	WEIGHT STACK GUIDE ROD(L=1400)	2
20	RUBBER DONUT	2
21	WEIGHT PLATE DECAL (10-200LBS)	1
a <b>5</b>	BOLT,HHCS,3/8"-16*2 3/4",L=70mm	2
b <b>2</b>	WASHER,FLAT,3/8"	2



NOTE: During each assembly step, ensure that all bolts and nuts are in place and partially threaded in before completely tightening any one bolt. Two people will be required to perform this procedure.




NOTE: During each assembly step, ensure that all bolts and nuts are in place and partially threaded in before completely tightening any one bolt.



#### Part list of step 5

	. are not or otop o		
ITEM	DESCRIPTION	QTY	
24	WEIGHT STACK FRAME SHIELD	2	
25	WEIGHT STACK SHIELD	1	
<b>a</b> 10	BOLT,BHCS,1/4"-20*1/4",L=8mm	10	
<b>a</b> 11	BOLT,BHCS,5/16"-18*3/4", L=16mm	4	
b3	WASHER,FLAT,5/16"	8	
с3	NUT, 5/16″-18	4	




# PRE-ASSEMBLY


### PART LIST:


ITEM	DESCRIPTION	QTY
В	ASSY, MAIN FRAME	1
С	ASSY,ARM	1
D	ASSY,BOOSTER	1
E	ASSY,FOOTLEVER	1
F	ASSY,PULL	1

B.ASSY,MAIN FRAME











E.ASSY,FOOTLEVER



F.ASSY,PULL



# PART LIST 1

#### PART LIST:

ITEM	DESCRIPTION	QTY
1	FOOT COVER 2"x2.75"	4
2	TOP CROSS BRACE	1
3	BOTTOM CROSS BRACE	1
4	CHROME WASHER ( Ф35*Ф11*5t )	5
5	CONNECT PLATE	2
6	NYLON COVER	2
7	PLASTIC INSERT CAP DIA(Ø32mm)	2
8	AXLE(Ø25*315)	2
9	GAS SPRING(30kg)	1
10	AXLE(Ø25*86)	1
11	CHROME WASHER ( Ф42*Ф13*4t )	2
12	BACK PAD	1
13	SEAT PAD	1
14	FOOT PLATE	2
15	LEFT FOOT TUBE	1
16	RIGHT FOOT TUBE	1
17	WEIGHT STACK	19
18	SELECTOR PIN	1
19	WEIGHT STACK GUIDE ROD(L=1400)	2
20	RUBBER DONUT	2
21	WEIGHT PLATE DECAL (10-200LBS)	1
22	NYLON PULLEY ASSEMBLY( 4.5")	5
23	CABLE RETAINER BRACKET(4.5")	3
24	WEIGHT STACK FRAME SHIELD	2
25	WEIGHT STACK SHIELD	1
26	PLASTIC INSERT CAP(50 × 70mm)	1
27	ADJUSTING TUBE	1
28	ASSY,PUSH PULL PIN (L=72mm)	1
29	PLASTIC INSERT CAP 2SQ.	1
30	POWDER METALLURGY BUSHING 1 IDx1 1/4 OD	8
31	PLASTIC INSERT CAP DIA(Ø48mm)	2
32	HANDLE (Ø24*165mm)	2
33	HANDLE (Ø24*380mm)	2
34	RUBBER BUMPER(3/8"-16)	1

#### HARDWARE LIST:

ITEM	DESCRIPTION	QTY
a <b>1</b>	BOLT,HHCS,1/2"-13*3 1/2", L=89mm	8
<b>a</b> 2	BOLT,BHCS,3/8"-16*3/4", L=18mm	5
a <b>3</b>	BOLT,HHCS,1/2"-13*1", L=25mm	2
a <b>4</b>	BOLT,HHCS,M8*40mm	2
a <b>5</b>	BOLT,HHCS,3/8"-16*2 3/4",L=70mm	4
a <b>6</b>	BOLT,HHCS,3/8"-16*1", L=25mm	2
a <b>7</b>	BOLT,HHCS,1/2"-13*3 3/4", L=95mm	2
a <b>8</b>	BOLT,HHCS,3/8"-16*2", L=50mm	3
a <b>9</b>	BOLT,HHCS,3/8"-16*3 3/4", L=95mm	2
a10	BOLT,BHCS,1/4"-20*1/4",L=8mm	10
<b>a</b> 11	BOLT,BHCS,5/16"-18*3/4", L=16mm	5
b <b>1</b>	WASHER,FLAT,1/2"	20
b <b>2</b>	WASHER,FLAT,3/8"	16
b3	WASHER,FLAT,5/16"	8
b <b>4</b>	WASHER,FLAT,M8	4
c1	LOCK NUT 1/2"-13	10
с2	LOCK NUT 3/8"-16	5
с3	NUT, 5/16″-18	4
c <b>4</b>	LOCK NUT M8	2
<b>d</b> 1	LOCK WASHER Ø13mm	2

#### CABLE LIST:

ITEM	DESCRIPTION	QTY
1#	<b>← 103</b>	1

### Hardware guide:

